

# Evaluating Cut Speed

## ALUMINUM

Cut speed too fast  
Cut drag lines are more than 15 degrees trailing the torch (torch movement right to left) High speed bottom dross, easy to remove



Cut speed correct  
Cut drag lines trail are visible, but cut surface is smooth No dross




Cut speed too slow  
Cut drag lines are more pronounced and cut surface is rougher



## STAINLESS STEEL (H35)


Cut speed too fast  
Gold heat discoloration swept in both directions Cut drag lines more than 15 degrees trailing High speed bottom dross, hard to remove



Cut speed correct  
Smooth cut surface No dross



Cut speed too slow  
Heat discoloration is concentrated in the bottom half of the cut Hard bottom dross, difficult to remove



## MILD STEEL (O2 PLASMA)

Cut speed too fast  
Trailing cut drag lines Light bottom dross, hard to remove, some top spatte



Cut speed correct  
Cut drag lines near vertical No dross



Cut speed too slow  
Cut drag lines lead the torch Heavy bottom dross, easy to remove



## MILD STEEL (AIR)

Cut speed too fast  
Cut drag lines curve and trail torch movement High speed bottom dross, hard to remove



Cut speed correct  
Cut drag lines near vertical Minimal dross



Cut speed too slow  
Cut drag lines vertical or leading the torch head Thicker bottom dross, easy to remove





[HOME](#) | [PRODUCT SOLUTIONS](#) | [PROCESS SOLUTIONS](#) | [KNOWLEDGE CENTER](#) | [CONTACT US](#) | [SITEMAP](#)  
COPYRIGHT THERMAL DYNAMICS AUTOMATION, ALL RIGHT RESERVED 2010

DESIGN BY: FOCUSMX.COM